

## Brilliant solution to common technical problems

حلول ساطعة للمشاكل المتكررة

### Dyeing :

**\*Cotton dyeings** prevent bleeding of poor wash fastness of reactive dyes,  
Just after over flow rinsing for 10 min,

Using 1 % **GBkol knit leveler/SN/SN2/RSA/MSD**  
( boiling two times for dark shades & one time for med.to light shades )  
& then 1 % **GBwash off co ( fixer )** if needed

**GBalkaline buffer & leveler** for the alkaline dyeing of PES fibers in order to avoid oligomer deposits  
as well as reactive dyeing leveling & buffer (no need to add alkali for fixation) & Replacing soda ash

**\*GBkol SN:** used as leveling for reactive dyeing specially for turquoise, blue and  
green`phthalosyanin`As well as is excellent protective colloid of all reactive dyes.  
And the only sequestering agent recommended to be used during reactive dyeings.

**\*GBvat leveler P :**unique leveling for `vat` indanthren dyeings, also is used as cationizing in  
exhaust pig. dyeing.

**\*GBleveler WO/PA :**Outstanding leveling for acid and acid metal dyeings

### **\*On PES dyeings machines :**

you will have a clean machine (Huspels, tube, cone, Jets....etc) & No oligomers  
within machine Pipes. When Using

2-4 % **GBojet** PELS/new

4- 6 g/l **GBhydro** Royal

6-8 g/l NaoH 38 Be For 45min. at 120° C



Cairo head office: 9,square 1163,El Shaheed Fouad Thabet St.,El Wozara square Sheraton Heliopolis.Cairo- Egypt

Tel: +20222683983, +201228099699 Fax : +202 2268466 E-mail: logistics@gb-chem.net , gbchem@gb-chem.net

Alex. Office :6, Talat Harab St.,Down Town Alexandria, Egypt

Tel.:+203 4819240, +201221148181 Fax:+203 4817565 E-mail: logistics@gb-chem.net , gbchemalex@gb-chem.net

## **\*Standard Recipes for Dyeing 100 % PES**

**\*اقوی الحلول لصباعة خامات البولى استر**

### 1- High Temperature Dyeing

#### **Dyeing:**

...% Disperse dyes  
1-2 g/l **GB**dispersing BL/WS (essential)  
0.5-1 g/l **GB**squestring TA-S  
1-3 % **GB**leveler SFD\*/SFD\* New  
PH 4-5 preferably adjusted with **GB**cid AS  
15-45min at 125 – 135 °C

**Reductive Clearing:** Just after over flow rinsing for 10 min,use  
2 – 4 **GB**reduction clearing ECO  
10-20min at 70-80 °C

**\* Using 3-4% **GB**leveler SFD\*/SFD\* New  
For 30min. at 130 °C will level any faulty dyeings.**

### 2- Continuous Dyeing

#### **Padding:**

... g/l Disperse dyes  
5-20 g/l **GB**antimigrating AM  
1-2 g/l **GB**detergent High Conc  
PH 6-7 preferably adjusted with **GB**cid AS  
Liquor pick-up 50-60 %

**Intermediate drying:** 110-130 °C

**Thermozoling:** 30-90 sec. at 200-225 °C

**GBojet BDS Very economical dispersing, sequestering and buffering versatile multi. purpose liquid auxiliary for use in polyester dyeing ... etc (one shot including nonvolatile Acid buffer).**



Cairo head office: 9,square 1163,El Shaheed Fouad Thabet St.,El Wozara square Sheraton Heliopolis.Cairo- Egypt

Tel: +20222683983, +201228099699 Fax : +202 2268466 E-mail: logistics@gb-chem.net , gbchem@gb-chem.net

Alex. Office :6, Talat Harab St.,Down Town Alexandria, Egypt

Tel.:+203 4819240, +201221148181 Fax:+203 4817565 E-mail: logistics@gb-chem.net , gbchemalex@gb-chem.net